Date: <u>12/28/05</u>

To: Alicia Barrera

Through: Bill Garrett/ Rob Wienke

From: Stephen Wittmer

Subject: Hudd Distribution Services Inc 5011 Firestone Place South Gate 90280

Inspection Request: Alicia Barrera

Determine the current operation; issue temporary permit if appropriate.

Inspection: 12/28/05

Contact: Freddie Varela, Maintenance

Findings:

- The facility is primarily a warehousing operation and transfer station for several large retail companies; including Wal-Mart.
- The only IW discharge is from a forklift and yard diesel cleaning operation.
- The wash pad is currently greater than 400 sq. ft., but it could easily be reduced to less than 400 sq. ft. to avoid the permit requirement.
- The maintenance of the yard diesels and the fork lifts is done by contract vendors.
- A letter should be send to David Fitzsimmons, Maintenance Supervisor that details the need for a reduction of area exposed to rainwater intrusion. The address is as follows:

David Fitzsimmons
Maintenance Supervisor
Hudd Distribution Services Inc.
5011 Firestone Place
South Gate, CA 90280-3591

Conclusion:

- The wash pad is currently greater than 400 sq. ft., but it could easily be reduced to less than 400 sq. ft. to avoid the permit requirement.
- A letter should be send to David Fitzsimmons, Maintenance Supervisor that details the need for a reduction of area exposed to rainwater intrusion. The address is as follows:

David Fitzsimmons
Maintenance Supervisor
Hudd Distribution Services Inc.
5011 Firestone Place
South Gate, CA 90280-3591